

**Ball Winders**

**Nancy's Knit Knacks LLC Price List 2017 effective Jan. 1, 2017 Rev.01**

Type	Primary difference	Part No.	Power	Yarn Guide	Description	USD Retail
Ball Winder	Basic unit	10000R	Crank	5/16"	Ball Winder, std pigtail	299
Ball Winder	Incl. Lge Pigtail	10005R	Crank	5/16, 1.0"	Ball Winder, standard and large pigtails	309
Ball Winder SDS	SDS Spindle	10000RSDS	Crank	5/16"	Ball Winder, SDS Spindle (no std. Spindle)	309
Elect Ball Winder	Incl. Motor	10001R	Motor,Crank	5/16"	Ball Winder and Power Base, std pigtail	699
Elect Ball Winder	Motor/Lge Pigtail	10006R	Motor,Crank	5/16, 1.0"	Ball Winder and Power Base, std/lge pigtail	709
Elect Ball Winder SDS	Motor/SDS	10001RSDS	Motor,Crank	5/16"	Ball Winder and Power Base, SDS Spindle	709
Cone Winder	Basic unit	10055R	Crank	5/16"	Cone Winder, std pig, SDS Spindle	345
Cone Winder+	Has both Spindles	10056R	Crank	5/16"	Cone Winder, std pig, SDS & Std Spindles	370
Elect Cone Winder	Incl. Motor	10059R	Motor,Crank	5/16"	Cone Winder & Power Base, std pigtail, SDS	745
Elect Cone Winder+	Motor/2 Spindles	10060R	Motor,Crank	5/16"	Cone Wndr & Power Base, std pig, SDS/Std	770
Cone Wdr Adapter	Converts BW to CW	10070R	NA	NA	Includes SDS & parts to convert BW to CW	55
Power Base - BW	None	10800R	Motor	NA	Power Base for use with Ball Winder	400
Motor	None	10826	24V	NA	PB Replacement Motor Hi-Torque R19	60
SDS-Small Dia.Spindle	None	10945	NA	NA	1.25" Dia. Spindle	32
SSDS-Super Small Dia	None	10947	NA	NA	0.375" Dia. Spindle, specialty use	45
Tens. Post & Arm Upg	None	10925	NA	NA	Converts orig Post/Arm w/scw to Knob sys.	20
Tension Post 5/16"	None	10951	NA	NA	Std. Post for use with knob	10
Tension Post 1.0"	None	10953	NA	NA	Opt. Post for use with knob, Art Yarn use	10
Tension Post Arm Upg	None	10946	NA	NA	Arm has slot for post (replaces screw post)	5
Ball Handle for BW	None	10902	NA	NA	Handle with 2" Ball end for Ball Winder	25
<b>Belts, O-rings, Motors</b>	<b>Color</b>	<b>Part No.</b>	<b>Dia.</b>	<b>Description</b>		
O-ring for BW	Black	10300	3/16"	Flange O-ring for BW (primary) set of 2	4	
O-ring for BW Spindle	Black	10302	3/16"	O-ring that fits over spindle, set of 4	4	
Drive Belt for Motor	Orange (was clear)	10355	1/4"	Belt that connects PBase & BW - set of 2	5	
L Bolt Assy for BW	Zinc	10912	5/16"	Holds BW to table (incl block and nut) - 1	5	

**Electronic Meters**

Elect Yarn Meter	None	30010R	12 VDC	5/16"	EYM on Power Base Stand 100-240 VAC	500
------------------	------	--------	--------	-------	-------------------------------------	-----

**Cores and Cones**

Yarn Ball Cores	White Acid-free	10510R	1.2"	3.5"	Mini-cores, 20/bag	6
Yarn Ball Cores	White Acid-free	10511R	1.2"	3.5"	Mini-cores, 50/box	15

**Cones**

Cones	Std cone finish	10600R		7"	Paper Cones 30 pack	15
Cones	Std cone finish	10600R		7"	Paper Cones 120 pack	53